



Внимание

Внимание

Монтаж и подключение электрооборудования должен выполнять квалифицированный электрик.

Недопустимо любое использование датчиков в оборудовании, от которого напрямую или косвенно зависит жизнь и здоровье людей, а также, которое может представлять опасность для людей, животных или имущества.

Электрическое подключение

Устройства сконструированы для низкого напряжения. При подключении устройства пользуйтесь технической документацией. При использовании пассивных датчиков (к примеру, PT1000 и тому подобных) в исполнении с 2-х проводной схемой подключения учитывайте сопротивление подключаемого кабеля. Высокий ток, проходящий через датчик, может внести погрешность в измерение, поэтому сила тока не должна превышать 1мА.

Монтаж


Устройства поставляются полностью подготовленными к эксплуатации. Закрепите датчик в воздуховоде с помощью монтажного фланца (входит в комплект).

Комплектация

1. Датчик ST-K1/PT1000
2. Монтажный фланец
3. Инструкция на русском языке

Схема подключения

Terminal Connection Plan



2-х проводное подключение
2-wire



Caution

Security Advice

The installation and assembly of electrical equipment may only be performed by a skilled electrician.

The modules must not be used in any relation with equipment that supports, directly or indirectly, human health or life or with applications that can result in danger for people, animals or real value.

Electrical Connection

The devices are constructed for the operation of protective low voltage (SELV). For the electrical connection, the technical data of the corresponding device are valid.

Specially with regard to passive sensors (e.g. PT1000 etc.) in 2-wire conductor versions, the wire resistance of the supply wire has to be considered.

Due to the self-heating, the wire current affects the accuracy of the measurement. Thus, the same should not exceed 1mA.

Mounting Advices

The model ST-K1/PT1000 can be mounted on the ventilation duct either by means of a mounting flange or by screws (Included).

Accessories

1. Sensor ST-K1/PT1000
2. Mounting flange
3. Datasheet

Размеры (мм)

Dimensions (mm)

