

# ScreenMaster AS

---

## Head office and main warehouse

PYROX AS

Postboks 110, Alnabru

N-0614 Oslo

NORWAY

Tel: +47 23 05 23 00

Fax: +47 23 05 23 21

E-mail: [export@pyrox.no](mailto:export@pyrox.no)

<http://www.pyrox.com>

## Sales office Russia and CIS countries

PYROX CIS

Arhangelskiy per. 7

RU-101000 Moscow

RUSSIA

Tel: +7 095 797 98 80

Fax: +7 095 797 98 81

E-mail: [pyrox.russia@sovintel.ru](mailto:pyrox.russia@sovintel.ru)

## Sales office Sweden

PYROX AB

Högboleden 33

S-774 61 Avesta

SWEDEN

Tel: +46 226 809 10

Fax: +46 226 809 15

E-mail: [eral@pyrox.se](mailto:eral@pyrox.se)

## Warehouse Sweden

PYROX AB


Industrivägen 3

S-73930 Skinnskatteberg

SWEDEN


# Pyrox

## *ScreenMaster AS*




# ScreenMaster AS

1.




	L	H	D	
<b>90LV</b>	900	190	175	mm
<b>90HV</b>	900	235	215	mm
<b>120LV</b>	1200	190	175	mm
<b>120HV</b>	1200	235	215	mm

2.




	A	B	E	F	G	
<b>90LV</b>	87	800	170	40	90	mm
<b>90HV</b>	95	770	217	40	135	mm
<b>120LV</b>	87	1100	170	40	90	mm
<b>120HV</b>	95	1080	217	40	135	mm

3.



4.



# ScreenMaster AS


---



	I	II	
<b>90LV</b>	625	820	m <sup>3</sup> /h
<b>90HV</b>	700	1100	m <sup>3</sup> /h
<b>120LV</b>	900	1350	m <sup>3</sup> /h
<b>120HV</b>	1100	1700	m <sup>3</sup> /h



<b>90LV</b>	8.7 kg	53 dB(A)
<b>90HV</b>	10.8 kg	60 dB(A)
<b>120LV</b>	11.4 kg	55 dB(A)
<b>120HV</b>	13.0 kg	60 dB(A)



(IP 44)